

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	332126	spring.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09
L2	11623	1 and (board PCB).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:02
L3	4493	2 and (force load pressure strain stress).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09
L4	986	3 and (sens\$4 detect\$4 transducer measur\$4 cell gage gauge).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09
L5	34	4 and (optoelectronic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09
L6	479	73/161.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:08
L7	1	6 and (optoelectronic)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09
L8	72	6 and spring.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:13
L9	62	8 and (force load pressure strain stress).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:09

EAST Search History

L10	55	9 and (sens\$4 detect\$4 transducer measur\$4 cell gage gauge).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:11
L11	85	"3628394" "3921445" "5798748"	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:12
L12	43	11 and spring	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT	OR	ON	2007/04/10 14:13